

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-005989**Date Inspected:** 05-Mar-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Haang Won Pang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Section 1AE & 1AW**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector Rory O'Kane was present during the times noted above for observations relative to the work being performed.

OBG Assembly Bay 2

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested by ZPMC MT personnel. This QA Inspector generated a TL-6028 MT report on this date. The weld designation numbers are as follows:

Segment # Weld Joint #

OBG 1AA SEG2E-009

OBG 1AA SEG2E-051

OBG 1AA SEG2E-465

OBG 1AA SEG2E-6391

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of CJP welds previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3. The QA Inspector observed no rejectable indications at the time of testing. The QA Inspector generated a TL-6027 UT report on this date. The weld identification numbers are as follows:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Segment # Weld Joint #

1AE/SEG004 SEG004A-002

1AE/SEG004 SEG004A-003

1AE/SEG004 SEG004A-008

1AE/SEG004 SEG004A-009

1AW/SEG003 SEG003A-002

1AW/SEG003 SEG003A-003

1AW/SEG003 SEG003A-005

1AW/SEG003 SEG003A-006

1AW/SEG003 SEG003A-008

1AW/SEG003 SEG003A-009

This QA Inspector reviewed the contract files and tracking logs for the Magnetic Particle Testing (MT), Ultrasonic Testing (UT), Welding Procedure Specifications (WPS), Procedure Qualification Records (PQR), and QC Inspector records to this date.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, who represents the Office of Structural Materials for your project.

Inspected By:	O'Kane,Rory	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
